

SECRET

OUT52334

SECRET 201704Z

NOV 20 18 17Z 20 NOV 1963

25X1

HFS ~~7/1~~
CJS ~~7/1~~
CPC ~~7/1~~
PMS ~~7/1~~
ACL ~~7/1~~

Grace (File)

1. CAMERA B 5 WAS USED IN MISSION 3774 FLOWN ON 16 NOVEMBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: INBOARD STATIC DISCHARGES AND EDGE FOG ON BOTH EDGES IS INTERMITTENT THROUGHOUT THE MISSION. A FINE PLUS DENSITY STREAK, WELL DEFINED AND VERY STRAIGHT, IS 3.25" FROM AND PARALLEL TO THE OUTBOARD EDGE FROM THE BEGINNING TO THE END OF THE MISSION. A FUZZY PLUS DENSITY STREAK APPROXIMATELY 0.2" WIDE, WANDERS FROM 2" TO 5.7" FROM THE OUTBOARD EDGE ALONG THE MAJOR AXIS THROUGHOUT THE MISSION.

C. 9L SIDE: MINOR, PRE-PROCESSING PLUS DENSITY STREAKS PARALLEL TO THE MAJOR AXIS AND INBOARD ROLLER CHATTER ARE CONTINUOUS THROUGHOUT THE MISSION. A MINUS DENSITY STREAK APPROXIMATELY 0.1" WIDE APPEARS 1.05" FROM AND PARALLEL TO THE INBOARD EDGE ON FRAMES 54 AND 61 THROUGH 66. A REPAIRED TEAR APPEARS ON FRAME 533.

D. BOTH SIDES: PINHOLES, EMULSION BLISTER AND PROCESSING STREAKS ARE MINOR AND INTERMITTENT THROUGHOUT THE MISSION.

Declassification Review by NGA/DoD

25X1

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

2

THERE ARE 629 FRAMES ON EACH SIDE OF THIS MISSION.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR
PROCESSING ANOMALIES.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD WHERE IT IS NOT DEGRADED BY
WEATHER.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 95 PER CENT OF
THIS MISSION.

S E C R E T

--END OF MESSAGE--